

Angle Grinder



**FACE SHIELD
MUST BE WORN**



**SAFETY GLASSES
MUST BE WORN**



**NO LOOSE
CLOTHING**



**LONG HAIR MUST
BE TIED BACK**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**

Bench Shears



**SAFETY GLASSES
MUST BE WORN**



**NO LOOSE
CLOTHING**



**LONG HAIR MUST
BE TIED BACK**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



**GLOVES MUST
BE WORN**

Brobo, Cold Metal Saw



**SAFETY GLASSES
MUST BE WORN**



**NO LOOSE
CLOTHING**



**LONG HAIR MUST
BE TIED BACK**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**

For more information see SAW, BANDSAW, METAL (VERTICAL) or SAW, BANDSAW, METAL (HORIZONTAL) on Equipment Safety in Schools

Metal Bandsaw



**FACE SHIELD
MUST BE WORN**



**SAFETY GLASSES
MUST BE WORN**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



**NO LOOSE
CLOTHING**



**LONG HAIR MUST
BE TIED BACK**



NO GLOVES

Milling Machine



**SAFETY GLASSES
MUST BE WORN**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



**NO LOOSE
CLOTHING**



**LONG HAIR MUST
BE TIED BACK**

For more information see LATHE, METAL (FIXED) on Equipment Safety in Schools (ESIS)

Metal Lathe



**FACE SHIELD
MUST BE WORN**



**SAFETY GLASSES
MUST BE WORN**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



**NO LOOSE
CLOTHING**



**LONG HAIR MUST
BE TIED BACK**

Mig Welder



**WELDING MASK
MUST BE WORN**



**WELDING
GAUNTLETS
MUST BE WORN**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



**LEATHER APRON
OR OVERALLS
MUST BE WORN**

For more information see WELDING, ELECTRIC ARC (STICK) on Equipment Safety in Schools (ESIS)

Electric Arc Welder (Stick)



**WELDING MASK
MUST BE WORN**



**WELDING
GAUNTLETS
MUST BE WORN**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



**LEATHER APRON
OR OVERALLS
MUST BE WORN**

Propane Brazing



**SAFETY GLASSES
MUST BE WORN**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



**LONG HAIR MUST
BE TIED BACK**



**WELDING
GAUNTLETS
MUST BE WORN**



Oxy Welding



**WELDING
GOGGLES MUST
BE WORN**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



**WELDING
GAUNTLETS
MUST BE WORN**



**LEATHER APRON
OR OVERALLS
MUST BE WORN**



**LONG HAIR MUST
BE TIED BACK**



Buffing Machine



**FACE SHIELD
MUST BE WORN**



**SAFETY GLASSES
MUST BE WORN**



**NO LOOSE
CLOTHING**



**LONG HAIR MUST
BE TIED BACK**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**

For more information see LINISHER METAL on Equipment Safety in Schools (ESIS)

Metal Linisher



**SAFETY GLASSES
MUST BE WORN**



**NO LOOSE
CLOTHING**



**LONG HAIR MUST
BE TIED BACK**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**

Spot Welder, Portable



**SAFETY GLASSES
MUST BE WORN**



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**

For more information see GUILLOTINE, SHEETMETAL (MANUAL) on Equipment Safety in Schools (ESIS)

Guillotine sheetmetal



**ENCLOSED
LEATHER FOOTWEAR
MUST BE WORN**



NO GLOVES

Magnabend



Panbrake

